

تقرير الفحص – 320DL كاتربيلر 2007

ساعات: ١٠٠٠٠ | الموقع: جزر الفارو | رقم التعريف: ٣٧١٧١٦

Key Features & Condition

N/A	Safety Certification Label
N/A	Ground Ripper
N/A	Ripper Control Valve
Yes	Low Ground Pressure Tracks
N/A	Operator's Manual
N/A	Emission Compliance Label
N/A	Grade Control System
N/A	Equipment Parts Manual
N/A	CAT System One

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Controls, Levers
Ok	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Ok	Warning alarms message
Ok	Washer, Wipers
Not cooling	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure, Gard
Ok	Electrical System

Engine & Performance

Electronic	Fuel Injection Type
Cat C9	Engine Model
Ok, need rust clean	Engine Cooling System
Ok	Engine Oil Check
Normal	Blowby



Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke
Ok, normal water	Coolant
Ok	Fluid Leaks

Exterior Condition & Visual Inspection

Ok	Doors, Covers, and Grilles
Ok	Access Steps & Handrails
Ok	Exterior Paint Condition
Ok	Blade Trunnions & Bushings
Ok	Underbody Protection Plates
Ok	Final Drive Condition
Ok	Fuel Tank, Roof, & Hood Condition
Ok	Lights and Battery Check
Ok	Pivot Shaft
Cracked on the left side	Push Arm
N/A	Tilt Linkage Pins & Bushings

Hydraulic System

Ok	Hydraulic Leaks
Ok	Lift Hydraulic Jacks
N/A	Ripper Lift Hydraulic Jacks
N/A	Tilt Hydraulic Jack
Ok	Angle Hydraulic Jack
N/A	Ripper Angle Hydraulic Jacks

Limited Functional Testing & Operation

Ok	Push Frame Pins
Ok	Blade Pins
N/A	Ripper Pins
Ok	Equalizer Bar Condition
Ok	Bulldozer Stall Test
Ok	Steering Function Test



Ok	Blade Tilt and Lift Test
Ok	Undercarriage Pivot Pins
Ok	Transmission Test
Ok	Brake System Test
Ok	Torque Converter Test

Blade Inspection

Ok	Blade Base Condition
Ok	Spill Rack Condition
Ok	Blade Front Condition
Ok	Blade Edge Condition

Undercarriage Inspection

-	Right Side Undercarriage Wear
80%	Undercarriage Bushings
80%	Undercarriage Shoes
80%	Front Idler Condition
80%	Rear Idler Condition
80%	Carrier Roller Condition
80%	Track Links Condition
80%	Sprocket Condition
80%	Roller Condition
80%	Track Canon Condition
80%	Track Width Measurement
-	Left Side Undercarriage Wear
80%	Undercarriage Bushings
80%	Undercarriage Shoes
80%	Front Idler Condition
80%	Rear Idler Condition
80%	Carrier Roller Condition
80%	Track Links Condition
80%	Sprocket Condition
80%	Roller Condition
70%	Track Canon Condition



W560, L 240, Grouser height 58 mm

Track Shose Measurement

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com