

Inspection report – 2009 Caterpillar 345D

Serial No: YEE00554 | Hours: 12979 | Location: United Arab Emirates | SKU: 2761

Key Features & Condition

| | |
|--------------------------------------|-----|
| Safety Certification Label | N/A |
| Automatic Lubrication System | N/A |
| Auxiliary Hydraulic Valve | N/A |
| Equipment Parts Manual | N/A |
| Air Conditioning System | N/A |
| Hydrostatic Drive System (Hydrostat) | N/A |
| Supplemental Steering System | N/A |
| Operator's Manual | N/A |
| Emission Compliance Label | N/A |
| Quick Attachment Coupler | N/A |
| Load Weighing System | N/A |
| Horn Function | N/A |

Operator Cabin Details

| | |
|-----------------------------------|--|
| Seat and Arm Support | Ok, need upholstery |
| Cab Doors & covers | Ok |
| Controls, Levers | Ok |
| Windows and Mirrors | Front and back windows are cracked, small window on right side is broken, side mirrors are missing |
| Dashboard Screen, Gauges | Ok, Coolant Temperature Gauge is not functional |
| Warning alarms message | Ok |
| Washer, Wipers | Ok |
| Air Conditioning & Heating System | Not functional |
| Cab Floor Covering | N/A |
| Cab Structure | Ok |
| Electrical System | Ok, need minor seervice |

Engine & Performance

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



| | |
|--------------------------|---|
| Fuel Injection Type | Electronic |
| Engine Model | Caterpillar C6.6 |
| Engine Cooling System | Ok |
| Engine Oil Check | Ok |
| Blowby | Normal |
| Exhaust System & Muffler | Ok, muffler minor damaged |
| Belts & Air/Oil Filters | Ok |
| Smoke | Normal |
| Coolant | Ok, normal water |
| Fluid Leaks | Ok, minor oil leak from oil pan gasket side |

Exterior Condition & Visual Inspection

| | |
|----------------------------|---|
| Main Frame and Lift Arm | Ok |
| Engine Hood | Ok |
| Access Steps and Handrails | Ok |
| Exterior Paint Condition | Ok |
| Counterweight Condition | Ok |
| Wheel Fenders | Ok, rear are missing |
| Lights Check | Need wiring joint, rear left is missing |
| Battery Check | Ok |

Power Train Inspection

| | |
|---------------------------|-----------|
| Axles and Differentials | Ok |
| Transmission Gearbox | Ok |
| Power Train force | Ok |
| Transmission Noise Check | Ok |
| Universal Joint Condition | Ok |
| Transfer Gear Type | Semi auto |

Hydraulic System

| | |
|------------------------------|-------------------------|
| Hydraulic Leaks | Ok |
| Lift and Tilt Hydraulic Jack | Ok |
| Steering Hydraulic Orbital | Ok |
| Steering Hydraulic Jacks | Ok, left minor oil leak |

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Hydraulic Pumps and Valves

Ok, solenoid valve need repair

Limited Functional Testing & Operation

| | |
|-----------------------------|----------------------------------|
| Steering Function Test | Ok |
| Transmission Operation Test | Ok |
| Loader Stall Test | Ok |
| Braking System Test | Ok, parking break not functional |
| Articulation Movement Check | Ok |
| Loader Attachment Pins | Ok, bucket pin minor loose |
| Supplemental Steering Test | N/A |

Attachments

| | |
|-------------------------------|-----------------------|
| Bucket Width and Capacity | W2500, H2350, D950 mm |
| Bucket Bottom Condition | Ok |
| Bucket Edge & Teeth Condition | Ok |
| Bucket Side Condition | Ok |
| Attachment Coupler | Ok |

Tires Inspection

| | |
|---|------------------|
| Front Right | - |
| Tire Brand & Size Details | Triangle 17,5R25 |
| Tire Remaining Life Percentage | 70% |
| Tire Condition Notes/ Wheel Rims & Nuts | Ok |
| Front Left | - |
| Tire Brand & Size Details | Triangle 17,5R25 |
| Tire Remaining Life Percentage | 60% |
| Tire Condition Notes/ Wheel Rims & Nuts | Ok |
| Rear Right | - |
| Tire Brand & Size Details | Maxam |
| Tire Remaining Life Percentage | 20% |
| Tire Condition Notes/ Wheel Rims & Nuts | Need change/ Ok |
| Rear Left | - |
| Tire Brand & Size Details | Triangle 17,5R25 |
| Tire Remaining Life Percentage | 60% |

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Tire Condition Notes/ Wheel Rims & Nuts

Ok

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

