

تقرير الفحص - 2022 كاتربيلر D3 320

ساعات: ٥٦٠٠ | الموقع: Dubai, الإمارات العربية المتحدة | رقم التعريف: ٣٦١٢٥٣

Machine Specifications

N/A	Safety Certification Label
Yes	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
N/A	Automatic Lubrication System
Yes	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
Yes	Hydraulic Hammer Lines
N/A	Grapple and Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System AddBlue
N/A	Stabilizer Blade Condition

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors and Covers
Ok	control levers, Control stick
Ok, No Mirrors	Windows and Mirrors
Ok	Dashboard Screen, Gauges and
Ok, climate system error message	Warning alarms message
Ok	Washer, Wipers
Not Cooling	Air Conditioning and Heating System
Ok	Cab Floor Covering
Ok, No Guard	Cab Structure, Gard
Ok	Electrical System

Engine & Performance

Electronic	Electronic Fuel Injection System
D13F	Engine Model
Ok	Engine Cooling System
Ok	Engine Oil Check



المعدات و الآليات | تقويم المزادات

Normal	Exhaust System and Muffler
Ok	Belts and Air/Oil Filters
Normal	Warning alarms, messages
ok	Coolant
Ok	Coolant condition

Exterior Condition & Visual Inspection

Ok	Main Frame and Track Frame
Ok	Protective Covers and Sheets
Ok	Engine Hood
Ok	Side Access Doors
Ok	Steps and Handrails
Ok	Storage Compartments
Ok	Boom Condition
Ok	Bumpers and Catwalk Condition
Ok	Arm Condition
Ok, Need Wiring Joint	Lights
Ok	Battery Check
Ok	Exterior Paint Condition

Hydraulic System

Minor oil leak from pump front gasket	Hydraulic Leaks
Ok	Boom Hydraulic Jack
Functional	Hydraulic Pump and Valve Block
Ok	Bucket Hydraulic Jack
Ok	Arm Hydraulic Jack
Bucket Cylinder	Welded Components

Limited Functional Testing & Operation

Ok	Boom Pins Condition
Ok	Excavator self- Drift Test
Ok	Arm Pins Condition
Ok, little noisy	Hydraulic Pump Noise Check
Need new bush, spacer, washer	Bucket Pins Condition



المعدات و الآليات | تقويم المزادات

Ok, little loose

Slewing Ring Bearing Movement Check

Ok

Swing Drive and Brake Test

Ok

Drive force Test

Attachments

digging bucket

Attachments model

W1530, H1200, D1050 mm

Size

Ok

Status

Ok

Coupler status

N/A

Second Attachments model

N/A

Size

N/A

Status

Undercarriage COMPONENT Remaining estimated LIFE

0.5

Bushings

0.5

Track shoes

0.5

Idlers

600 mm

:Shoe width in mm

80 mm

:Track pitch in mm

0.3

carrier rollers

0.3

Track rollers

0.3

Track links

0.3

Sprocket segments

يتم تقديم أي صمامات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصرياً.



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com