

## Inspection report – 2018 Aliva AL 262

Serial No: 252500 | Hours: 200 | Location: Achill Sound, Ireland, Albania | SKU: 11279

---

### Key Features & Condition

Safety Certification Label	N/A
Ground Ripper	N/A
Ripper Control Valve	N/A
Low Ground Pressure Tracks	Yes
Operator's Manual	N/A
Emission Compliance Label	N/A
Grade Control System	N/A
Equipment Parts Manual	N/A
CAT System One	N/A

---

### Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	Ok
Air Conditioning & Heating System	Not cooling
Cab Floor Covering	Ok
Cab Structure, Gard	Ok
Electrical System	Ok

---

### Engine & Performance

Fuel Injection Type	Electronic
Engine Model	Cat C9
Engine Cooling System	Ok, need rust clean
Engine Oil Check	Ok
Blowby	Normal

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok, normal water
Fluid Leaks	Ok

---

## Exterior Condition & Visual Inspection

Doors, Covers, and Grilles	Ok
Access Steps & Handrails	Ok
Exterior Paint Condition	Ok
Blade Trunnions & Bushings	Ok
Underbody Protection Plates	Ok
Final Drive Condition	Ok
Fuel Tank, Roof, & Hood Condition	Ok
Lights and Battery Check	Ok
Pivot Shaft	Ok
Push Arm	Cracked on the left side
Tilt Linkage Pins & Bushings	N/A

---

## Hydraulic System

Hydraulic Leaks	Ok
Lift Hydraulic Jacks	Ok
Ripper Lift Hydraulic Jacks	N/A
Tilt Hydraulic Jack	N/A
Angle Hydraulic Jack	Ok
Ripper Angle Hydraulic Jacks	N/A

---

## Limited Functional Testing & Operation

Push Frame Pins	Ok
Blade Pins	Ok
Ripper Pins	N/A
Equalizer Bar Condition	Ok
Bulldozer Stall Test	Ok
Steering Function Test	Ok

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Blade Tilt and Lift Test	Ok
Undercarriage Pivot Pins	Ok
Transmission Test	Ok
Brake System Test	Ok
Torque Converter Test	Ok

---

## Blade Inspection

Blade Base Condition	Ok
Spill Rack Condition	Ok
Blade Front Condition	Ok
Blade Edge Condition	Ok

---

## Undercarriage Inspection

Right Side Undercarriage Wear	-
Undercarriage Bushings	80%
Undercarriage Shoes	80%
Front Idler Condition	80%
Rear Idler Condition	80%
Carrier Roller Condition	80%
Track Links Condition	80%
Sprocket Condition	80%
Roller Condition	80%
Track Canon Condition	80%
Track Width Measurement	80%
Left Side Undercarriage Wear	-
Undercarriage Bushings	80%
Undercarriage Shoes	80%
Front Idler Condition	80%
Rear Idler Condition	80%
Carrier Roller Condition	80%
Track Links Condition	80%
Sprocket Condition	80%
Roller Condition	80%
Track Canon Condition	70%

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Track Shose Measurement

W560, L 240, Grouser height 58 mm

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

