

Inspection report – 2000 KUBOTA SVL75-2

Km: 255.0 | Location: Dubai, Faroe Islands | SKU: 367787

Key Features & Condition

Safety Certification Label	N\A
Diesel fuel	Ok
Housing	Ok
On Wheels	N\A

Housing

Sheet Metal	Ok
Frames	Ok, Minor dint
Guards / Screens	Ok
Doors	Ok
Paintwork	Ok

Engine

Model	Cummins QSL9G5
Leaks	Ok
Oil Condition	Ok
Exhaust	Ok
Smoke	Normal
Injection	Electronic
Noises	Ok
Cooling System	Ok
Blow By	Normal
Belts	Ok
Fluid Levels	Ok

Generator

Noises	Ok
Cables	N\A
Sockets	N\A

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT AUCTIONS

Damages	Ok
Switchboard	Ok
Gauges	Ok
Warning messages	1117 power lost with ignition, 1246 general Engine fault

Tank / Fuel System

Fuel Hoses	Ok
Tank	Ok
Leaks	Ok
Gauge Tank	N\A

Others

Safety Switches	Ok
Rated Power kVA	330KVA
Regenerative power, kW	47.0
Fuses	Ok
If on Wheels	N\A
Tire Condition	N\A
Draw Bar	N\A
Lights	N\A
Alt voltage	399 V

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

