

Inspection report – 2015 Caterpillar 966H

Location: Jeddah, Ukraine | SKU: 371056

Key Features & Condition

Safety Certification Label	N/A
Ground Ripper	N/A
Ripper Control Valve	N/A
Low Ground Pressure Tracks	Yes
Operator's Manual	N/A
Emission Compliance Label	N/A
Grade Control System	N/A
Equipment Parts Manual	N/A
CAT System One	N/A

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	Ok
Air Conditioning & Heating System	Not cooling
Cab Floor Covering	Ok
Cab Structure, Gard	Ok
Electrical System	Ok

Engine & Performance

Fuel Injection Type	Electronic
Engine Model	Cat C9
Engine Cooling System	Ok, need rust clean
Engine Oil Check	Ok
Blowby	Normal

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok, normal water
Fluid Leaks	Ok

Exterior Condition & Visual Inspection

Doors, Covers, and Grilles	Ok
Access Steps & Handrails	Ok
Exterior Paint Condition	Ok
Blade Trunnions & Bushings	Ok
Underbody Protection Plates	Ok
Final Drive Condition	Ok
Fuel Tank, Roof, & Hood Condition	Ok
Lights and Battery Check	Ok
Pivot Shaft	Ok
Push Arm	Cracked on the left side
Tilt Linkage Pins & Bushings	N/A

Hydraulic System

Hydraulic Leaks	Ok
Lift Hydraulic Jacks	Ok
Ripper Lift Hydraulic Jacks	N/A
Tilt Hydraulic Jack	N/A
Angle Hydraulic Jack	Ok
Ripper Angle Hydraulic Jacks	N/A

Limited Functional Testing & Operation

Push Frame Pins	Ok
Blade Pins	Ok
Ripper Pins	N/A
Equalizer Bar Condition	Ok
Bulldozer Stall Test	Ok
Steering Function Test	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Blade Tilt and Lift Test	Ok
Undercarriage Pivot Pins	Ok
Transmission Test	Ok
Brake System Test	Ok
Torque Converter Test	Ok

Blade Inspection

Blade Base Condition	Ok
Spill Rack Condition	Ok
Blade Front Condition	Ok
Blade Edge Condition	Ok

Undercarriage Inspection

Right Side Undercarriage Wear	-
Undercarriage Bushings	0.8
Undercarriage Shoes	0.8
Front Idler Condition	0.8
Rear Idler Condition	0.8
Carrier Roller Condition	0.8
Track Links Condition	0.8
Sprocket Condition	0.8
Roller Condition	0.8
Track Canon Condition	0.8
Track Width Measurement	0.8
Left Side Undercarriage Wear	-
Undercarriage Bushings	0.8
Undercarriage Shoes	0.8
Front Idler Condition	0.8
Rear Idler Condition	0.8
Carrier Roller Condition	0.8
Track Links Condition	0.8
Sprocket Condition	0.8
Roller Condition	0.8
Track Canon Condition	0.7

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Track Shoe Measurement

W560, L 240, Grouser height 58 mm

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

