

## Rapport d'inspection – 1988 Dynapac CA25

Numéro de série: 4971407 | Lieu: Dubai, Émirats arabes unis | SKU: 11188

---

### Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	Yes
Adjustable Boom System	N/A
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	Yes
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	Yes
Grapple and Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System AddBlue	N/A
Stabilizer Blade Condition	N/A
Horn	Ok

### Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok, mirrors are missing
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	Ok
Air Conditioning & Heating System	Ok
Cab Floor Covering	Ok
Cab Structure, Gard	Ok
Electrical System	Ok

### Engine & Performance

Fuel Injection System	Electronic
Engine Model	SAA6D125E-5
Engine Cooling System	Ok

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Engine Oil Check	Ok
Cooling System	Ok
Coolant	Ok, normal water
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke Check	Normal
Blowby	Normal
Leaks & Seals	Ok

---

## Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok
Protective Covers & Sheets	Ok
Engine Hood	Ok
Side Access Doors	Ok
Steps and Handrails	Ok
Boom Condition	Ok
Bumpers & Catwalk Condition	Ok
Arm Condition	Ok
Lights	Missing
Battery Check	Ok
Cabin Compartments	Ok
Exterior Paint Condition	Ok, repainted

---

## Hydraulic System

Hydraulic Leaks	Ok
Boom Hydraulic Jack	Ok
Hydraulic Pump & Valve Block	Ok
Bucket Hydraulic Jack	Ok
Arm Hydraulic Jack	Ok

---

## Performance analysis

Boom Pins Condition	Ok
Excavator self- Drift Test	Ok
Arm Pins Condition	Ok

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Hydraulic Pump Noise Check	Ok
Bucket Pins Condition	Ok
Slewing Ring Bearing Movement Check	Ok
Swing Drive and Brake Test	Ok
Drive force Test	Ok

---

## Attachments

Attachments model	Bucket
Size	W1500, H1200, D90 mm
Status	Ok
Coupler status	Ok
Second Attachments model	N/A
Size	N/A
Status	N/A

---

## Undercarriage

bushings	70%
Track shoes	80%
idlers	80%
shoe width in mm:	600 mm
track pitch in mm:	75 mm
carrier rollers	70%
Track rollers	70%
Track links	70%
Sprocket segments	70%

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

