

Rapport d'inspection – 1991 Dynapac CA25

Numéro de série: 4971407 | Lieu: Dubai, Émirats arabes unis | SKU: 12772

Key Features & Condition

Safety Certification Label	N/A
Equipment Parts Manual	N/A
Horn Function	Yes
Travel Alarm	N/A
Operator's Manual	N/A
Emission Compliance Label	N/A
Emergency switch	N/A
Park Brake	N/A
Closed Cabin	N/A

Operator Cabin Details

Seat and Arm Support	Ok
Control Levers, Control Swithes	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Windows& mirrors	Windows N/A, mirrors Ok
Wiper, washer	N/A
Electrical System	Ok
Cabin Structure	Ok, open cabin
Floor cover mat	N/A

Engine & Performance

Fuel Injection System Type	Mechanical
Fluid Leaks	Ok
Engine Oil Check	Ok
Exhaust System and Muffler	Ok
Exhaust Smoke	Normal
Engine Model Details	CUMMINS 4BTAA3.9-99C
Engine Cooling System	Ok



Engine Blow-by Check	Normal
Belts and Air/Oil Filters	Ok, filters need change
Coolant	Ok

Exterior Condition & Visual Inspection

Chassis	Ok
Engine Hood	Ok, lifting jack cylinder has a minor leak
Stairs, Handrails	Ok
Paintwork	Ok
Water Tanks	N/A
Drum Condition	Ok
Rubber Drum Isolators	Ok
Drum Scraper	Ok
Lights	Ok
Batteries	Need change

Hydraulic System

Hoses & Lines	Ok
Drum Vibration Motors	Ok
Pumps & Valves	Ok
Steering Cylinders	Ok
Hydraulic Tank	Ok

Limited Functional Testing & Operation

Steering	Functional
Transmission Test	Ok
Dash Console	N/A
Brake/Park Brake	Ok
Water spray system	N/A
Drive Motors front	Ok
Drive Motors rear	Ok
Drum Vibration	Ok

Tires - mm (%)

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Right
Left

30% need change
20% need change

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

