

**Rapport d'inspection – 2000 KUBOTA SVL75-2**

Km: 255.0 | Lieu: Dubai, Îles Féroé | SKU: 367787

**Key Features & Condition**

Safety Certification Label	N\A
Diesel fuel	Ok
Housing	Ok
On Wheels	N\A

**Housing**

Sheet Metal	Ok
Frames	Ok, Minor dint
Guards / Screens	Ok
Doors	Ok
Paintwork	Ok

**Engine**

Model	Cummins QSL9G5
Leaks	Ok
Oil Condition	Ok
Exhaust	Ok
Smoke	Normal
Injection	Electronic
Noises	Ok
Cooling System	Ok
Blow By	Normal
Belts	Ok
Fluid Levels	Ok

**Generator**

Noises	Ok
Cables	N\A
Sockets	N\A

**PANDE Auctions LLC**

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

# PLANT & EQUIPMENT AUCTIONS

Damages	Ok
Switchboard	Ok
Gauges	Ok
Warning messages	1117 power lost with ignition, 1246 general Engine fault

## Tank / Fuel System

Fuel Hoses	Ok
Tank	Ok
Leaks	Ok
Gauge Tank	N\A

## Others

Safety Switches	Ok
Rated Power kVA	330KVA
Regenerative power, kW	47.0
Fuses	Ok
If on Wheels	N\A
Tire Condition	N\A
Draw Bar	N\A
Lights	N\A
Alt voltage	399 V

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

## PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

