

Rapport d'inspection – 2005 Mitsubishi Fuso

Lieu: Jeddah, Émirats arabes unis | SKU: 371153

Key Features & Condition

Safety Certification Label	N/A
Automatic Lubrication System	N/A
Auxiliary Hydraulic Valve	N/A
Equipment Parts Manual	N/A
Air Conditioning System	Not functional
Hydrostatic Drive System (Hydrostat)	N/A
Supplemental Steering System	N/A
Operator's Manual	N/A
Emission Compliance Label	N/A
Quick Attachment Coupler	N/A
Load Weighing System	N/A
Horn Function	No

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Ok,dashboard screen need replace
Warning alarms message	Ok
Washer, Wipers	Ok
Air Conditioning & Heating System	Not functional
Cab Floor Covering	Ok
Cab Structure, Gard	Ok
Electrical System	Ok

Engine & Performance

Fuel Injection Type	Electronic
Engine Model	C7.1

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
SmOke	Normal
Coolant	Ok,normal water
Fluid Leaks	Ok

Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok
Engine Hood	Ok
Access Steps and Handrails	Ok
Exterior Paint Condition	Ok
Counterweight Condition	Ok
Wheel Fenders	Ok,rear fenders are missing
Lights Check	Ok
Battery Check	Ok

Power Train Inspection

Axles and Differentials	Ok
Transmission Gearbox	Ok
Power Train force	Ok
Transmission Noise Check	Ok
Universal Joint Condition	Ok
Transfer Gear Type	Semi auto

Hydraulic System

Hydraulic Leaks	Ok,one hose minor leak
Lift and Tilt Hydraulic Jack	Ok,hydraulic jack canon is welded
Steering Hydraulic Orbital	Ok
Steering Hydraulic Jacks	Ok
Hydraulic Pumps and Valves	Ok



Limited Functional Testing & Operation

Steering Function Test	Ok
Transmission Operation Test	Ok
Loader Stall Test	Ok
Brake System Test	Ok
Articulation Movement Check	Ok
Loader Attachment Pins	Ok, 3 pins minor loose
Electrical System Check	Ok
Supplemental Steering Test	Ok

Attachments

Bucket Width and Capacity	W3000, H1450, D1200 mm
Bucket Bottom Condition	Ok, minor welding
Bucket Edge & Teeth Condition	Ok
Bucket Side Condition	Ok
Attachment Coupler	Ok

Tires Inspection

Front Right	-
Tire Brand & Size Details	TRIANGLE 23.5R25
Tire Remaining Life Percentage	50%
Tire Condition Notes	Ok
Wheel Rims & Nuts	one missing
Front Left	-
Tire Brand & Size Details	TRIANGLE 23.5R25
Tire Remaining Life Percentage	70%
Tire Condition Notes	Ok
Wheel Rims & Nuts	Ok
Rear Right	-
Tire Brand & Size Details	TRIANGLE 23.5R25
Tire Remaining Life Percentage	40%
Tire Condition Notes	Minor cuts
Wheel Rims & Nuts	Ok
Rear Left	-

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT AUCTIONS

Tire Brand & Size Details	TRIANGLE 23.5R25
Tire Remaining Life Percentage	60%
Tire Condition Notes	Minor cuts
Wheel Rims & Nuts	Ok

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

