

## Rapport d'inspection – 2022 Hamm 1104

Km: 658675.0 | Lieu: Curaçao | SKU: 420653

---

### Key Features & Condition

|                                     |     |
|-------------------------------------|-----|
| Safety Certification Label          | N/A |
| Boom Hydraulic Check Valve          | Yes |
| Adjustable Boom System              | N/A |
| Automatic Lubrication System        | N/A |
| Arm Hydraulic Check Valve           | Yes |
| Diesel Particulate Filter           | N/A |
| Hydraulic Hammer Lines              | Yes |
| Grapple and Shear Hydraulic Lines   | N/A |
| Diesel Exhaust Fluid System AddBlue | N/A |
| Stabilizer Blade Condition          | N/A |
| Horn                                | Ok  |

---

### Operator Cabin Details

|                                   |                         |
|-----------------------------------|-------------------------|
| Seat and Arm Support              | Ok                      |
| Cab Doors & covers                | Ok                      |
| Control Levers, Control Stick     | Ok                      |
| Windows and Mirrors               | Ok, mirrors are missing |
| Dashboard Screen, Gauges          | Ok                      |
| Warning alarms message            | Ok                      |
| Washer, Wipers                    | Ok                      |
| Air Conditioning & Heating System | Ok                      |
| Cab Floor Covering                | Ok                      |
| Cab Structure, Gard               | Ok                      |
| Electrical System                 | Ok                      |

---

### Engine & Performance

|                       |             |
|-----------------------|-------------|
| Fuel Injection System | Electronic  |
| Engine Model          | SAA6D125E-5 |
| Engine Cooling System | Ok          |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                          |                  |
|--------------------------|------------------|
| Engine Oil Check         | Ok               |
| Cooling System           | Ok               |
| Coolant                  | Ok, normal water |
| Exhaust System & Muffler | Ok               |
| Belts & Air/Oil Filters  | Ok               |
| Smoke Check              | Normal           |
| Blowby                   | Normal           |
| Leaks & Seals            | Ok               |

## Exterior Condition & Visual Inspection

|                             |               |
|-----------------------------|---------------|
| Main Frame & Track Frame    | Ok            |
| Protective Covers & Sheets  | Ok            |
| Engine Hood                 | Ok            |
| Side Access Doors           | Ok            |
| Steps and Handrails         | Ok            |
| Boom Condition              | Ok            |
| Bumpers & Catwalk Condition | Ok            |
| Arm Condition               | Ok            |
| Lights                      | Missing       |
| Battery Check               | Ok            |
| Cabin Compartments          | Ok            |
| Exterior Paint Condition    | Ok, repainted |

## Hydraulic System

|                              |    |
|------------------------------|----|
| Hydraulic Leaks              | Ok |
| Boom Hydraulic Jack          | Ok |
| Hydraulic Pump & Valve Block | Ok |
| Bucket Hydraulic Jack        | Ok |
| Arm Hydraulic Jack           | Ok |

## Performance analysis

|                            |    |
|----------------------------|----|
| Boom Pins Condition        | Ok |
| Excavator self- Drift Test | Ok |
| Arm Pins Condition         | Ok |

## PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                                     |    |
|-------------------------------------|----|
| Hydraulic Pump Noise Check          | Ok |
| Bucket Pins Condition               | Ok |
| Slewing Ring Bearing Movement Check | Ok |
| Swing Drive and Brake Test          | Ok |
| Drive force Test                    | Ok |

## Attachments

|                          |                      |
|--------------------------|----------------------|
| Attachments model        | Bucket               |
| Size                     | W1500, H1200, D90 mm |
| Status                   | Ok                   |
| Coupler status           | Ok                   |
| Second Attachments model | N/A                  |
| Size                     | N/A                  |
| Status                   | N/A                  |

## Undercarriage

|                    |        |
|--------------------|--------|
| bushings           | 70%    |
| Track shoes        | 80%    |
| idle               | 80%    |
| shoe width in mm:  | 600 mm |
| track pitch in mm: | 75 mm  |
| carrier rollers    | 70%    |
| Track rollers      | 70%    |
| Track links        | 70%    |
| Sprocket segments  | 70%    |

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

## PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

