

## Rapport d'inspection – 2022 Caterpillar 966H

Lieu: Jeddah, Émirats arabes unis | SKU: 437122

---

### Specifications and Standards

Air Conditioning System	Yes
With Crane	N/A
Dump Truck Deck	Yes
Spare Tire	Yes
Fire Extinguisher	Yes
Towing Attachment	N/A
Recovery	N/A
Xenon Headlights	N/A
Seat Belt	Yes
Android secreen	Yes
Tire Tools	Yes

---

### Interior

Seats	Ok
Switches	Ok
Gauges	Ok
Aircon / Heater	Ok
Ceiling	Ok
Cab Doors	Ok
Windows	Ok
Wipers	Ok
Floor Mates	Ok

---

### Engine

Fuel Injection Type	Electronic
Fuel Type	Diesel
Model	4JJ1E2N
Leaks	Ok
Oil Condition	Ok

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Exhaust	Ok
Cooling System	Ok
Sound	Normal
Blow By	Normal
Belts	Ok
Power	Ok
Coolant	Ok

---

## Exterior

Main Frame Structure	Ok
Body Metal	Ok
Door Handle Condition	Ok
Exterior Paint Condition	Ok
Radiator Grill Condition	Ok
Bumper Condition	Ok
Light Condition	Ok
Battery Condition	Ok

---

## Power Train

Axels	Ok
Gearbox	Ok
Transmission Gear	Ok
Transfer Gear	Ok
Universal Joints	Ok
Differentials	Ok
Brake Drums/Disk	Ok

---

## Limited Functional Test

Drive Forward	Ok
Drive Reverse	Ok
Service Brake	Ok
Steering	Ok
Wheel Bearing	Ok
Suspensions	Ok

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Park Brake	Ok
Tipper Hyd Jack	Ok

---

## Tires Axle 1

RHS mm (%) rem.	80%
LHS mm (%)	80%
Cuts	Ok
Recapped	N/A
Year Model	2024

---

## Tires Axle 2

RHS mm (%) rem.	80%
LHS mm (%)	80%
Cuts	Ok
Recapped	N/A

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

